




# Inspection Report

<b>Report No:</b> 235184	<b>Manufacturer:</b> Airquee Ltd	
<b>Tag No:</b> 49297	<b>Size:</b> 3.85m x 3.1m x 2.9m	
<b>Date:</b> 27 Jul 2023	<b>Type:</b> Bouncy Castle	
	<b>Serial Number:</b> P44132_C	

## Automated Test Sheet

Anchorage		Detail	Totally Enclosed Details		Detail	Additional Details		Detail
Anchor Points	Pass	164	Exits	N/A		Anchor Type	PVC & metal triang	
Anchor Accessories	Pass	16/380	Exit Markings	N/A		Number of Anchors	6	
<b>Structure</b>			Independent Support	N/A		Open Side Fall-off Height	0.48M	
Seam Security	Pass	Webbed	Emergency Lighting	N/A		Inside Wall Height	1.05M	
Stitching	Pass	4-5mm	Deflation of the User Area	N/A		Play Area	4m2	
Blower Tube	Pass	1.47m	<b>Slides</b>			Max User Height	<i>Max No. Users</i>	
Walls & Towers	Pass	3mm/1 degree	Height of Walls	N/A		1.0 metre	4	
Step/Ramp Size	Pass	1.2/2.65	Run Out	N/A		1.2 metre	3	
Grounding	Pass	85kg	Clamber Net	N/A		1.5 metre	2	
Sharp Angles	Pass	None	Slide Sheet	N/A		1.8 metre	2	
Pressure	Pass	5.8"	<b>Blower</b>					
Fall Off Height	Pass	0.48	Suitability	Pass	100%	Place of Test	Romania	
Trough Depth	Pass	80/580	Inlet and Outlet Mesh	Pass	Clean	<b>Notes:</b>		
Entrapment	Pass	None	Cable and Plug	Pass	Good			
Stability	Pass		Impeller	Pass	Clean			
Deflation/Evacuation	Pass	+10 seconds	Return Flap	Pass	1 piece			
Air Loss	Pass	None	PAT Test	Pass	Green light			
Markings	Pass	Side	Blower Type	Gibbons				
Identification	Pass	Front	Blower Size	1.5 HP				
<b>Materials</b>			<b>Risk Assessment Notes:</b>					
Fabric (Fire)	Pass	Tested						
Fabric Strength	Pass	Assuming						
Zips	Pass							
Thread	Pass	Wax						
Ropes	N/A							
Netting	Pass	2 mm						
Windows	N/A							
Artwork	Pass	Printed						

## Annual Test

I certify that the inflatable play equipment identified by means of the PIPA tag attached to the unit (number as above) was tested in accordance with the European Standard BS EN 14960 and

# PASSED

If you suspect that this report is not genuine or has been altered, you can check the equipment's test status by visiting [www.pipa.org.uk](http://www.pipa.org.uk) and entering the tag number shown above. Please report any irregularities using the contact details below.



**Report Expiry Date:** 26 Jul 2024

**Inspection Body:** The Bouncy Castle Man

**Print Name:** Mark Eaglesham

**Signature:**