




# Inspection Report

<b>Report No:</b> 235185	<b>Manufacturer:</b> Airquee Ltd	
<b>Tag No:</b> 50957	<b>Size:</b> 4.6m x 3.7m x 2.9m	
<b>Date:</b> 27 Jul 2023	<b>Type:</b> Bouncy Castle with Slide (Combo)	
	<b>Serial Number:</b> P46386_A	

## Automated Test Sheet

Anchorage		Detail	Totally Enclosed Details		Detail	Additional Details		Detail
Anchor Points	Pass	164	Exits	Pass		Anchor Type	PVC & Metal triang	
Anchor Accessories	Pass	16/380	Exit Markings	N/A		Number of Anchors	7	
<b>Structure</b>			Independent Support	Pass		Open Side Fall-off Height	0.43M	
Seam Security	Pass	Webbed	Emergency Lighting	N/A		Inside Wall Height	1.05M	
Stitching	Pass	4-5mm	Deflation of the User Area	Pass		Play Area	6m2	
Blower Tube	Pass	1.5m	<b>Slides</b>			Max User Height	Max No. Users	
Walls & Towers	Pass	0 mm, 0 degr	Height of Walls	Pass	0.55	1.0 metre	6	
Step/Ramp Size	Pass	1.2/2.7	Run Out	Pass	750/1100	1.2 metre	5	
Grounding	Pass	85kg	Clamber Net	Pass	Foam step	1.5 metre	4	
Sharp Angles	Pass	None	Slide Sheet	Pass	Sliding Mat.	1.8 metre	4	
Pressure	Pass	5.5"	<b>Blower</b>					
Fall Off Height	Pass	0.43	Suitability	Pass	100%	Place of Test	Romania	
Trough Depth	Pass	90/500	Inlet and Outlet Mesh	Pass	Clean	<b>Notes:</b>		
Entrapment	Pass	None	Cable and Plug	Pass	Good			
Stability	Pass		Impeller	Pass	Clean			
Deflation/Evacuation	Pass	+10 seconds	Return Flap	Pass	1 piece			
Air Loss	Pass	None	PAT Test	Pass	Green light			
Markings	Pass	Side	Blower Type	Gibbons				
Identification	Pass	Front step	Blower Size	1.5HP				
<b>Materials</b>			<b>Risk Assessment Notes:</b>					
Fabric (Fire)	Pass	Tested						
Fabric Strength	Pass	Assuming						
Zips	Pass	1 covered						
Thread	Pass							
Ropes	N/A							
Netting	Pass	2mm						
Windows	N/A							
Artwork	Pass	Printed						

## Annual Test

I certify that the inflatable play equipment identified by means of the PIPA tag attached to the unit (number as above) was tested in accordance with the European Standard BS EN 14960 and

# PASSED

If you suspect that this report is not genuine or has been altered, you can check the equipment's test status by visiting [www.pipa.org.uk](http://www.pipa.org.uk) and entering the tag number shown above. Please report any irregularities using the contact details below.



**Report Expiry Date:** 26 Jul 2024

**Inspection Body:** The Bouncy Castle Man

**Print Name:** Mark Eaglesham

**Signature:**